Declas	sified in Part - Sanitized Copy A	pproved for Release 2013/11/20 : CLASSIFIED MESSAGE	CIA-RDP67B00329R000100130038-9
DATE	2543Z 15 AUG 63	SECRET	1 Commo & Intel 2 11 5 SA 3 DEC & DITECH RB
TO :	DIRECTOR		Elin 50X1 50X1
ACTION:	05A 1-15		ROUTINE
.	TOR: 0718Z 15 AUG 63		IN 87344
TO	ADIC CARD HBJAYWALK ELINT	DOCUMENT NO	50X1
	REF A B CARD 0053	☐ DECLASSIFIED CLASS, CHANGED TO: TS NEXT REVIEW DATE: AUTH: HR 70-2 DATE://////REVIEWE	
	FOLLOWING MODIFICATION MADE TO SYSTEM SIX DUPING EQUIPMENT RECEIVED FROM HQS AND IT IS BELIEVED THIS WILL ELIMINATE MOST OF TROUBLES DUE TO OUTPUT OF COMMAND RECEIVER BEING RECORDED ON CHANNEL 2. OUTPUT OF W. B. O. DAGW WAS DEVOUED.		

RECEIVED FROM HQS AND IT IS BELIEVED THIS WILL ELIMINATE MOST OF TROUBLES DUE TO OUTPUT OF COMMAND RECEIVER BEING RECORDED ON CHANNEL 2. OUTPUT OF V.R.O. RACK WAS REMOVED FROM INPUT TO REFERENCE TONE CHANNEL AND CONNECTED TO X BAND CHANNEL AND AMPLIFIER. THIS SUPERIMPOSES V.R.O. ON X BAND DATA CHANNEL AND AS ANALYST MUST MONITOR X BAND AT ALL TIMES TO CORRELATE SYSTEM TWELVE, THIS CHANGE ELIMINATED MOST OF TROUBLES WITH MASTER RECORDER TAPE COPYING. TO POSSIBLE ELIMINATE ALL OTHER TROUBLES REQUEST THAT REFERENCE AND SWITCHING TONES BE RECORDED RELACITY HIGHER THAN COMMAND RECEIVER. SYSTEM TWELVE BLANKING PULSES SHOULD BE RECORDED AS HIGH AS POSSIBLE FOR QUICK LOCATION,

50X1

END OF MESSAGE

SECRET

GROUP 1 Excluded from automatic covergrading and declassification